

- Certain areas of the community are served by transite (asbestos cement) water mains, which tend to be brittle and often break during adjacent construction or during freeze-thaw. A potential health hazard also exists when the asbestos cement pipe breaks down over time. These pipe segments should be replaced with modern technologies to bring the system up to current standards.




Figure 6.7 - Potable Water System