

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 4486 GLEN MEYERS CERT # 8926

Site Information

Parcel Description: wever

Address: 3638 190th st, Wever, IA 52658

County: Lee

Owner Information

Property is owned by a business: No

Business Name:

Owner Name: Marigold LLLP

Email Address:

Address: 3638 190th st, Wever, IA 52658

Phone No:

Site related information

No Of Bedrooms: 2

Facility Type: Residential

Last Occupied: 04/11/2023

Permit issued by County: Yes

All plumbing fixtures enter septic system: Yes

Property Information Comments:

Inspection Date: 04/10/2023

Currently Occupied: No

System Installation Date: 07/27/2017

Permit Number: 183

County contacted for records: Yes

Primary Treatment

Fairfield

Tank Name: Fairfield

Tank Material: Concrete

No. of Compartments: 2

Date Pumped: **4/10/2023**

Distance To Well (Ft.): over 100

Risers Intact: Yes

Type: Septic Tank

Tank Corrosion Type: None

Pump Tank Chamber: No

Meets Setback to Well: Yes

Is Accessible: Yes

Effluent Filter Present: Yes

Tank Size (Gal): 1250

Liquid Level Type: Normal

Licensed Pumper Name: st-99

Well Type: Unknown

Lid Intact: Yes

Watertight: Yes

Tank/Vault Pumped: Yes Tank Comments:	Inlet Baffle Present: Yes	Outlet Baffle Present: Yes	Functioning as Designed: Yes
General Primary Treatment Com	ments:		
Distribution Type			
Distribution System : No			
General Distribution System Con	nments : System has a hand	made header pipe	
Secondary Treatment			
Secondary Treatment: No			
General Secondary Treatment Co	omments: System has 155 fe	et of laterals	
Narrative Report			
TOT Inspection Report Overall N	arrative Comments:		
After doing this inspection th		date!!	
We had to haul up water to d This system was put in per ch date installed!!			

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 4486 GLEN MEYERS CERT # 8926

Owner Name:

Marigold LLLP

Address:

3638 190th st , Wever , IA 52658

County:

Lee

Inspection Date:

04/10/2023

Submitted Date:

4/11/2023

This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).





